

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Biloxi Decon Area	Facility Location ID:	BX01
Assessment Date :	8/30/2010	Incident Name :	BP Spill
Physical Location :	164 8th Street		
City, State :	Biloxi, MS	County :	Harrison

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	
5. How many samples were collected?	
Additional Comments : 2 partially full roll-offs containing damaged algae boom destined for energy recovery were on site along with one rolloff partially full of non-contaminated PPE. Mr. Hensley said no oily boom has been processed at this facility. A new oily vessel decon area has recently been established. All liquids and solids generated from decontamination operations are manifested for disposal as oil-contaminated. No concerns regarding waste management practices were noted during the visit.	